## PURCHASE ORDER

DBM - GPPB-TSO **Entity Name** Supplier: FLEETSERV INC. P.O. No.: PO-AD-2024-012 Address: 3rd Avenue, Brgy. Bagong Lipunan ng Date: 30 April 2024 Crame, Quezon City TIN: 008-902-419 Mode of Procurement : Section 53.9 (Negotiated Procurement) Small Value Procurement) of the Revised IRR of RA 9184 Gentlemen: Please furnish this Office the following articles subject to the terms and conditions contained herein Place of Delivery: Government Procurement Policy Board -- Technical Support Office Building Delivery Term: <u>five (5) calendar days upon receipt of the</u> (GPPB-TSO) Building, Commonwealth Avenue, UP Diliman Campus, Quezon City Purchase Order Date of Delivery: five (5) calendar days upon Payment Term : Land Bank's LDDAP-ADA/Bank Transfer facility receipt of the Purchase Order Stock/ Unit Description Quantity **Unit Cost** Property No. Amount Lot Repair and Maintenance of GPPB-TSO Official Vehicles (Including Tires 282,100.00 P 282,100.00 and Batteries) Preventive Maintenance Service: I. Scope of Work a. Service Provider (SP) must diagnose/ check-up the following vehicles: i. Nissan Urvan NV350 2018 (SAB9273) -107,618km check-up -Replacement of Motor Oil (Fully synthetic) Inspection and replacement of Oil filter -Engine Flushing Replacement of Fuel filter Replacement of Air filter Replacement of Power Steering Fluid Inspection and replacement of Gear Oil Inspection and replacement of Differential Oil -Inspection and replacement of Brake Fluid -Inspection and replacement of Coolant Inspection of Serpentine Belt Inspection of Timing Belt Component -Battery Health Check -Inspection and repair of Auxiliary Motor Fan -EGR and Intake/Exhaust Manifold Cleaning -Inspection, cleaning, leak test of Aircon System and flushing system
 -Inspection and replacement of evaporator Inspection and refill of Freon Inspection of Capilla Oil Inspection of Cabin Filter Inspection of Receiver Drier -Expansion valve front -Expansion valve rear -Cooling Coil Inspection and cleaning of Condenser Inspection of Compressor Inspection of Shock absorber, rear and front -Tire rod -Rack End -Ball Joint -Wheel Hub Bearing Inspection of Brake pad, Brake Shoe and Rotor Disc. Inspection of Clutch disc, Pressure plate, Release bearing, Pilot bearing, Primary clutch master cylinder, Secondary cylinder Inspection and repair of Power Window Mechanism Inspection and correction of other parts Front wipers, Tires, Head light, Brake light, Park light, Wheel alignment and balancing, Camber. ii. Nissan Urvan NV350 2018 (SAB8443) -97,760km check up -Replacement of Motor Oil (Fully synthetic) Inspection and replacement of Oil filter -Engine Flushing -Replacement of Fuel filter -Replacement of Air filter Inspection and replacement of Gear Oil Inspection and replacement of Differential Oil Inspection and replacement of Brake Fluid Inspection and replacement of Coolant Inspection of Serpentine Belt Inspection of Timing Belt Component -Battery Health Check Replacement of Battery Size: N70/3SMF, 75ah

> PERNADETTE S. CELIS Business Manager
> FleetSERV I
> Phone 7585 4358 / Fax /234 4540

-Inspection and repair of Auxiliary Fan Motor EGR and Intake/Exhaust Manifold Cleaning -Inspection, cleaning, leak test of Aircon System and flushing system -Inspection of evaporator -Inspection and refill of Freon -Inspection of Capilla Oil -Inspection of Cabin Filter Inspection of Receiver Drier -Expansion valve front -Expansion valve rear -Cooling Coil Inspection and cleaning of Condenser Inspection of Compressor Inspection of Shock absorber, rear and front -Tire rod -Rack End -Ball Joint -Wheel Hub Bearing Inspection of Brake pad, Brake Shoe and Rotor Disc -Inspection of Clutch disc, Pressure plate, Release bearing, Pilot bearing, Primary clutch master cylinder, Secondary cylinder

Inspection and correction of other parts Front wipers, Tires, Head light, Brake light, Park light, Wheel alignment and balancing, Camber. -Replacement of Tires Quantity: 2 **Tubeless** Width: 195 Height: 80mm Diameter: 15" iii. Toyota Innova 2016 (SAB9272) -116,464km check up -Replacement of Motor Oil (Fully synthetic) Inspection and replacement of Oil filter -Engine Flushing -Replacement of Air filter -Inspection and replacement of Gear Oil -Inspection and replacement of Differential Oil Inspection and replacement of Brake Fluid Inspection and replacement of Coolant Inspection of Serpentine Belt -Inspection of Timing Belt Component -Battery Health Check -Inspection and repair of Auxiliary Motor Fan -EGR and Intake/Exhaust Manifold Cleaning -Inspection, cleaning, leak test of Aircon System and flushing system -Inspection and replacement of evaporator -Inspection and refill of Freon -Inspection of Capilla Oil Inspection of Cabin Filter -Inspection of Receiver Drier -Expansion valve front Expansion valve rear -Cooling Coil Inspection and cleaning of Condenser -Inspection of Compressor Inspection of Shock absorber, rear and front -Tire rod -Rack End -Ball Joint -Wheel Hub Bearing Inspection and replacement of rear wheel cylinder
 Inspection and replacement of front wheel cylinder Inspection of Brake pad, Brake Shoe and Rotor Disc Inspection and cleaning of Drum Brake -Adjustment of Hand brake cable -Battery health check -Inspection and correction of other parts Front wipers, Tires, Head light, Brake light, Park light, Wheel alignment and balancing, Camber. -Replacement of Tires Quantity: 4 Tubeless Width: 205 Height: 65mm Diameter: 15" iv. Toyota Innova 2013 (SLA925/ABE1082) -Replacement of Tires Quantity: 4

Tubeless Width: 205 Height: 65mm Diameter: 15"

BERNADETTE S. CELIS
Business Managar
FleetSERV Inc.
Phone 7585 4358 / Fax 7239 4340
Mobile 09175378886

	v. Toyota Innova 2017 (VQ7372) -Replacement of Tires Quantity: 4 Tubeless Width: 205 Height: 65mm Diameter: 15°		
	vi. Toyota GL Grandia (SAB9271) -Replacement of Tires Quantity: 4 Tubeless Width: 195 Height: R15C		
	Diameter: 106/104S		
	b. SP shall ensure availability of its service, manpower, and availability of parts. The actual duration of the maintenance shall be agreed upon by the End-User and SP in consideration of the nature and complexity of the service.		
	c. SP warrants that replacement of parts, tools, and materials to be used for the automative service shall be appropriate to the type and model of the vehicle.		
	d. SP warrants that the vehicle under the maintenance services shall be safe and secure while in the custody of the contractor.		
	e. During the check-up, SP shall send a list of parts that are found t be defect5ive and needs to be replaced.		
	<b>Delivery Requirements:</b> End-User will coordinate the schedule of Preventive Maintenance for each vehicle within five (5) calendar days upon receipt of the Purchase Order		
	******nothing follows******		Press
(Total Amount	in Words) Two Hundred Eighty-Two Thousand One Hundred Pesos Only		PHP 282,100.00
Contract ma make the project government polic Conforme:	y be terminated in those or in part, at any time specified above, a penalty of one-tenth (1/10) of or y be terminated in those or in part, at any time for the convenience of the Government upon the implementation of the Government upon th	irty (30) days' written notice, if determined s, but not limited to, fortuitous event/s or of Very truly yours,	the existence of conditions changes in law, and national 05/02/2024  ERA- GUILLERMO of Authorized Official Director IV
Fund Cluster: 01 Funds Available: Php 282,100.00		ORS/BURS No. : Date of the ORS/BURS:	
	1/ 1	Amount :	
	HARRY A. CURAZA/ Signature over Printed Name of Accountant IV	Amount.	